#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Yes

No

N/A

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

# WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-028018 Address: 333 Burma Road **Date Inspected:** 21-Jul-2012

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

**CWI Name:** See below. **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** 

**Delayed / Cancelled:** 34-0006 **Bridge No: Component:** OBG

## **Summary of Items Observed:**

Quality Assurance Inspector (QA) Fritz Belford was at the American Bridge/Fluor (ABF) job site at Yerba Buena Island in California between the times noted above in order to monitor Quality Control functions and the in process work being performed by ABF personnel. The following items were observed:

## OBG

This QA randomly observed ABF/JV qualified welder James Zhang #6001 performing Shielded Metal Arc Welding (SMAW) with 3.2mm diameter E7018H4R electrode and implementing Caltrans approved Welding Procedure Specification's (WPS) ABF-WPS-D15-1040C-CU. The joint being welded was corner drop in designated as 12W/13W-C1.1.

During welding, ABF Quality Control (QC) Salvador Moreno was noted monitoring the welding parameters.

Approximately 10:00 this QA observed QC Sal Moreno performing Magnetic Particle Testing (MT) of Complete Joint Penetration (CJP) back gouge designated as 12W/13W-C1.1.

#### Observation of QCUT

This QA randomly observed ABF qualified Non Destructive Testing (NDT) Technician Bernard Docena perform Ultrasonic Testing (UT) of Complete Joint Penetration (CJP) weld 13W PPW 123 W2.1 BF2

## **Ultrasonic Testing**

This QA performed Ultrasonic Testing (UT) on approximately 460mm of Longitudinal Stiffener Complete Joint Penetration (CJP) splice welds at 13W/14W LS2 and LS3 were inspected using this testing method.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This weld was previously accepted by QC Ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3.

This QA observed no rejectable indications at the time of testing. This QA generated a TL-6027 UT report on this date. The completed work observed at this location appeared to be in compliance with the contract specifications.

This weld is a Seismic Performance Critical Member (SPCM) member.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

# **Summary of Conversations:**

Conversations relevant to work performed on this date.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy - (510) 385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Belford,Fritz	Quality Assurance Inspector
Reviewed By:	Levell,Bill	QA Reviewer